

Tablica 2.5. Dozvoljena odstupanja za izabrana prioritetna tolerancijska

Naz. mera mm iznad....do	D10	E9	F7	H6	H7	H8	H9	H11	J7	J8	K7	K8	M7
1 ...3	+60 +20	+39 +14	+16 +6	+6 0	+10 0	+14 0	+25 0	+60 0	+4 -6	+6 -8			0 -12
3... 6	+78 +30	+50 +20	+22 +10	+8 0	+12 0	+18 0	+30 0	+75 0	+6 -6	+10 -8			0 -12
6... 10	+98 +40	+61 +25	+28 +13	+9 0	+15 0	+22 0	+36 0	+90 0	+8 -7	+12 -10	+5 -10	+6 -16	0 -15
10... 18	+120 +50	+75 +32	+34 +16	+11 0	+18 0	+27 0	+43 0	+110 0	+10 -8	+15 -12	+6 -12	+8 -19	0 -18
18... 30	+149 +65	+92 +40	+41 +20	+13 0	+21 0	+33 0	+52 0	+130 0	+12 -9	+20 -13	+6 -15	+10 -23	0 -21
30... 50	+180 +80	+112 +50	+50 +25	+16 0	+25 0	+39 0	+62 0	+160 0	+14 -11	+24 -15	+7 -18	+12 -27	0 -25
50... 80	+220 +100	+134 +60	+60 +30	+19 0	+30 0	+46 0	+74 0	+190 0	+18 -12	+28 -18	+9 -21	+14 -32	0 -30
80... 120	+260 +120	+159 +72	+71 +36	+22 0	+35 0	+54 0	+87 0	+220 0	+22 -13	+34 -20	+10 -25	+16 -38	0 -35
120....180	+350 +145	+185 +85	+93 +43	+25 0	+40 0	+63 0	+100 0	+250 0	+26 -14	+41 -22	+12 -28	+20 -43	0 -40
180 ...250	+355 +170	+215 +100	+96 +50	+29 0	+46 0	+72 0	+115 0	+290 0	+30 -16	+47 -25	+13 -33	+22 -50	0 -46
250... 315	+400 +190	+240 +110	+108 +56	+32 0	+52 0	+81 0	+130 0	+320 0	+36 -16	+55 -26	+16 -36	+25 -56	0 -52
315... 400	+440 +210	+265 +125	+119 +62	+36 0	+57 0	+88 0	+140 0	+360 0	+39 -18	+60 -29	+17 -40	+28 -61	0 -57
400... 500	+480 +230	+290 +135	+131 +68	+40 0	+63 0	+97 0	+155 0	+400 0	+43 -20	+66 -31	+18 -45	+29 -68	0 -63

NAPOMENA: U sistemu zajedničke spoljne mere preporučuju se sledeća naleganja:

h5	h6	h8	h9	h11	h12	h13
+		+			+	+

h5	h6	h8	h9	h11	h12	h13
+		+			+	+

h5	h6	h8	h9	h11	h12	h13
+		+			+	+

Naleganje sa zazorom

A11						
B9		+				
B11				+		
C9		+				
C11						
D9		+		+		
D10						
D11					+	
E8		+				
E9						
F7		+	+			
F8						
G6	+					
G7						

Naleganje sa zazorom

H6	+					
H7						
H8						
H9						
H11						
H12						
H13						

Neizvesna naleganja

J6	+					
J7		+				
K6						
K7		+				
M6	+					
M7		+				
N6	+					
N7		+				

Naleganje sa preklonom

P6	+					
P7		+				
R6	+					
R7		+				
S6	+					
S7		+				
T6	+					
T7		+				
U6	+					
U7		+				
X6	+					
X7		+				
Z6	+					
Z7		+				
Z8			+			
ZA7	+					
ZA8		+				
ZB8			+			
ZB9				+		
ZC8		+				
ZC9			+			

Naleganja 1. stepena prioriteta

Naleg. 3. stepena prioriteta

Za ograničena područja mera

Naleganja 2. stepena prioriteta

■ Naleganja 1. stepena prioriteta
 ▨ Naleganja 2. stepena prioriteta

⊕ Naleg. 3. stepena prioriteta
 ⊞ Za ograničena područja mera

polja za unutrašnje mere

Naz. mera mm iznad....do	M8	N7	N8	P7	R7	S7	S8	T7	T8	T9	U8	X8	C11
1 ... 3		-4 -14		-6 -16	-10 -20	-14 -24	-14 -28					-20 -34	+120 +60
3... 6		-4 -16	-2 -20	-8 -20	-11 -23	-15 -27	-19 -37					-28 -46	+145 +70
6... 10	+1 -21	-4 -19	-3 -25	-9 -24	-13 -28	-17 -32	-23 -45					-34 -56	+170 +80
10... 14	+2 -25	-5 -23	-3 -30	-11 -29	-16 -34	-21 -39	-28 -55					-40 -67	+205
14... 18												-45 -72	+95
18... 24	+4 -29	-7 -28	-3 -36	-14 -35	-20 -41	-27 -48	-35 -68					-54 -87	+240
24 ... 30								-33 -54	-41 -74	-41 -93	-48 -81	-64 -97	+110
30 ... 40	+5 -34	-8 -33	-3 -42	-17 -42	-25 -50	-34 -59	-43 -82	-39 -64	-48 -87	-48 -110	-60 -99	-80 -119	+280 +120
40 ... 50								-45 -70	-54 -93	-54 -116	-70 -109	-97 -136	+290 +130
50... 65	+3 -41	-9 -39	-4 -50	-21 -51	-30 -60	-42 -72	-53 -99	-55 -85	-66 -112	-66 -140	-87 -133	-122 -168	+330 +140
65 ... 80					-32 -62	-48 -78	-59 -105	-64 -94	-75 -121	-75 -149	-102 -148	-146 -192	+340 +150
80... 100	+6 -48	-10 -45	-4 -58	-24 -59	-38 -73	-58 -93	-71 -125	-78 -113	-91 -145	-91 -178	-124 -178	-178 -232	+390 +170
100...120					-41 -76	-66 -101	-79 -133	-91 -126	-104 -158	-104 -191	-144 -198	-210 -264	+400 +180
120...140					-48 -88	-77 -117	-92 -155	-107 -147	-122 -185	-122 -222	-170 -233	-248 -311	+450 +200
140...160	+8 -55	-12 -52	-4 -67	-28 -68	-50 -90	-85 -125	-100 -163	-119 -159	-134 -197	-134 -234	-190 -253	-280 -343	+460 +210
160...180					-53 -93	-93 -133	-108 -171	-131 -171	-146 -209	-146 -246	-210 -273	-310 -373	+480 +230
180...200					-60 -106	-105 -151	-122 -194	-149 -195	-166 -238	-166 -281	-236 -308	-350 -422	+530 +240
200...225	+9 -63	-14 -60	-5 -77	-33 -79	-63 -109	-113 -159	-130 -202	-163 -209	-180 -252	-180 -295	-258 -330	-385 -457	+550 +260
225...250					-67 -113	-123 -169	-140 -212	-179 -225	-196 -268	-196 -311	-284 -356	-425 -497	+570 +280
250...280	+9 -72	-14 -66	-5 -86	-36 -88	-74 -126	-138 -190	-158 -239	-198 -250	-218 -299	-218 -348	-315 -396	-475 -556	+620 +300
280...315					-78 -130	-150 -202	-170 -251	-220 -272	-240 -321	-240 -370	-350 -431	-525 -606	+650 +330
315...355	+11 -78	-16 -73	-5 -94	-41 -98	-87 -144	-169 -226	-190 -279	-247 -304	-268 -357	-268 -408	-390 -479	-590 -679	+720 +360
355...400					-93 -150	-167 -244	-208 -297	-273 -330	-294 -383	-294 -434	-435 -524		+760 +400
400...450	+11 -86	-17 -80	-6 -103	-45 -108	-103 -166	-209 -272	-232 -319	-307 -370	-330 -427	-330 -485	-490 -587		+840 +440
450...500					-109 -172	-229 -292	-252 -349	-337 -400	-360 -457	-360 -515	-540 -637		+880 +480