

	$z_1$	$z_2$	$m_n$ mm	$b$ mm	$n_1$ o/min	$T_1$ Nm	Ležaji izlaznog vratila
1.	24	64	2,5	60	750	100	6208
2.	24	60	2,5	60	850	100	6208
3.	23	55	3	60	950	110	6208
4.	23	53	3	60	1000	110	6208
5.	22	48	3	60	750	120	6208
6.	22	46	3	60	850	120	6208
7.	21	41	4	60	950	140	6208
8.	21	48	4	65	1000	140	6009
9.	20	44	4	65	750	160	6009
10.	20	42	4	65	850	160	6009
11.	19	47	4	65	950	180	6209
12.	19	45	4	65	1000	180	6209
13.	24	48	4	65	750	200	6209
14.	24	40	5	65	850	200	6209
15.	20	44	4	72	950	220	6209
16.	20	40	5	65	1000	220	6209
17.	19	47	4	72	750	200	6010
18.	19	45	4	65	850	200	6209
19.	24	56	3	65	950	180	6209
20.	24	50	4	65	1000	180	6209
21.	23	49	4	65	750	160	6009
22.	24	42	3	52	750	100	6208
23.	24	46	3	60	850	100	6208
24.	23	45	3	60	950	110	6208
25.	23	47	3	60	1000	110	6208
26.	22	40	3	60	750	120	6208
27.	22	44	3	60	850	120	6208
28.	21	42	4	60	950	140	6208
29.	21	47	4	65	1000	140	6009
30.	20	45	4	65	750	160	6009
31.	20	56	3	60	850	100	6208
32.	19	49	3	60	950	100	6208
33.	19	49	3	60	1000	110	6208
34.	24	64	3	60	750	110	6208
35.	24	60	3	60	850	120	6208
36.	20	54	3	65	950	120	6009
37.	20	52	3	60	1000	100	6208
38.	19	47	3	60	750	100	6208
39.	19	45	3	60	850	110	6208
40.	24	40	3	60	950	110	6208
41.	24	48	3	60	1000	120	6208
42.	23	43	3	60	750	120	6208
43.	24	44	4	60	750	140	6208
44.	24	56	3	65	850	140	6009
45.	23	50	4	65	950	160	6009
46.	23	49	4	65	1000	160	6009
47.	22	64	3	72	750	180	6010
48.	22	60	3	72	850	180	6010
49.	21	55	3	72	950	200	6010
50.	21	49	4	72	1000	200	6209
51.	20	48	4	72	750	220	6010
52.	20	46	4	72	850	220	6010
53.	19	39	5	65	950	200	6209
54.	19	48	4	72	1000	200	6010
55.	24	44	4,5	65	750	180	6209
56.	24	64	3	65	850	180	6209
57.	20	60	3	72	950	160	6009
58.	20	56	3	60	1000	100	6208
59.	19	53	3	60	750	100	6208
60.	19	49	3	60	850	110	6208
61.	24	46	3	60	950	110	6208
62.	24	40	3	60	1000	120	6208
63.	23	49	3	60	750	120	6208